MIDMARK®

Installation/Operation Instructions

9A14400X & 9A20800X KNEE CRUTCH ASSEMBLY

KIT COMPONENTS

Part Number	Description	Qty.
9A144002	Knee Crutch Assembly	1
or		
9A144004	Knee Crutch Clamp Assembly	1
or		
9A208002	Knee Crutch Assembly	1
003-0733-00	Installation / Operation Instructions	1

REQUIRED TOOLS

Phillips screwdriver with 7"-8" (17.8-20.3 cm) shaft and magnetic tip to hold screw.
7/32" Allen wrench (qty. 2)
9/16" Open end wrench

INTRODUCTION

To support the knee and legs for pelvic examinations.

WARNING
Do not use simultaneously with a 9A21300X Caster Base Assembly.

INSTALLATION (1)



A. Extend both stirrups all the way out.
B. Remove three mounting screws and washers on each stirrup housing.
C. Remove housings.
D. Remove hole plugs from stirrup mount weldments.

INSTALLATION (2)



A. Place knee crutch support weldments in position.
B. Secure with 3/8"-16 x 7/8" bolts and 3/8"-16 nuts provided with kit.
C. Place stirrup housing in position.
D. Secure with three screws.
E. Push in stirrups.

© Midmark Corporation - 1998

OPERATION



A. Loosen handle.
B. Insert knee crutch assembly to desired height.
C. Rotate knee crutch to desired position.
D. Tighten handle.

OPERATION (9A208002 KNEE CRUTCH)



A. Loosen handle.
B. Rotate knee crutch to desired position.
C. Tighten handle.

MIDMARK®
Midmark Corporation, Versailles, Ohio 45380 U.S.A.
(937) 526-3662 FAX (937) 526-5542

© Midmark Corporation - 1998